National Transportation Safety Board NTSB ID: DEN02LA019 Aircraft Registration Number: N902AM FACTUAL REPORT Occurrence Date: 01/11/2002 Most Critical Injury: None Occurrence Type: Accident Investigated By: NTSB Location/Time Nearest City/Place State Zip Code Local Time Time Zone CO 80010 0840 **MST** Aurora Distance From Landing Facility: Direction From Airport: Airport Proximity: Off Airport/Airstrip Aircraft Information Summary Aircraft Manufacturer Model/Series Type of Aircraft

Sightseeing Flight: No Air Medical Transport Flight: No

Narrative

McDonnell Douglas

Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:

On January 11, 2002, at approximately 0840 mountain standard time, a McDonnell Douglas MD 902 helicopter, N902AM, operated by MD Helicopters, was substantially damaged during a hard landing in a field near Aurora, Colorado. The flight instructor, a pilot receiving instruction, and one passenger were not injured. Visual meteorological conditions prevailed, and no flight plan was filed for this local training flight being conducted under Title 14, CFR Part 91. The flight originated from Centennial Airport, Englewood, Colorado, at approximately 0750.

MD 902

According to the instructor, he was conducting transition training and was demonstrating emergency procedures on anti-torque malfunctions and loss of thrust/fixed pedal settings. After reaching final approach at approximately 80 knots forward airspeed, and at approximately 100 feet above ground level, he began to demonstrate how to complete an approach with a loss of directional control or "Anti-Torque Failure- Fixed Thruster Setting." He identified an intended termination area, and established the helicopter on a "shallow" approach angle with a deceleration attitude of approximately 15 to 20 degrees nose up and approximately 300 feet per minute rate of descent. The flight profile "appeared normal" until about 50 to 60 feet above ground level when the helicopter started to descend at a higher than desired rate for demonstration. The pilot applied collective lever control and a shudder was felt in the rotor system, followed by an increase in descent rate. Collective lever application could not arrest the descent. The helicopter struck the ground hard in a nose high attitude, ballooned into the air approximately 3 to 5 feet and slowly rotated The "thruster" was jammed in the neutral position and the "fan would approximately 360 degrees. stall making popping sounds," but he had no problem landing the helicopter from a hover with power. The helicopter sustained substantial damage to the Notar (No Tail Rotor) Anti-Torque rotating thruster cone, the aft cross tube, and both landing gear skids.

The pilot stated that he encountered "vortex-ring-state" while trying to slow the helicopter, and that it "put me on the ground at a very high rate of descent." The initial higher rate of descent may have been due to the higher density altitude at the training site than is normally encountered at his home station in Mesa, Arizona.

At 0853, the reported weather at Centennial Airport (APA), Englewood, Colorado (approximately 12 nautical miles west of the accident site, and at an elevation of 5,883 feel msl) was, wind, 220 degrees at 8 knots; visibility, 10 statute miles; sky condition, few at 12,000 feet; temperature, 7 degrees C. (44.6 degrees F.); dew point, minus 12 degrees C. (10.4 degrees F.); altimeter setting, 30.24. The calculated density altitude was 6,022 feet msl.

Helicopter

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: DEN02LA019

Occurrence Date: 01/11/2002

AVIATION	rrence T	ence Type: Accident												
Landing Facility/Approach Inf	formation													
Airport Name			Airport II	D:	Airport Eleva	tion	Run	way Used	Runwa	y Lengtl	_ength Runv		Width	
					Ft.	MSL								
Runway Surface Type: Unknown		I												
Runway Surface Condition: Unkno	 own													
Type Instrument Approach: Unknown														
VFR Approach/Landing: Unknown														
Aircraft Information														
Aircraft Manufacturer			- 1		Series						Number			
McDonnell Douglas	M	ID 90)2					900-0	00092					
Airworthiness Certificate(s): Normal														
Landing Gear Type: Skid														
Homebuilt Aircraft? No	Cer	Certified Max Gross Wt.					6250 LBS Numbe			r of Engines: 2				
• • • • • • • • • • • • • • • • • • • •					Engine Manufacturer: Model/Series: Pratt & Whitney PCE-BG0027							Rated Power: 800 HP		
- Aircraft Inspection Information														
Type of Last Inspection			Date of Last Inspection				Time Si	nce Last Insp	Airfram	e Total	Γime			
100 Hour			01/200	01/2002					8.01 Ho	ours		38.0	1 Hours	
- Emergency Locator Transmitter (•						
ELT Installed? No	ELT Opera	ited? No)	ELT Aided in Locating Accident Site? No										
Owner/Operator Information														
Registered Aircraft Owner			Stre	Street Address 37 West, 100 South										
Zion Credit Corporation			City	City								Zip	p Code	
				Salt Lake City								84	101	
Operator of Aircraft			Street Address 4555 E McDowell Rd											
MD Helicopters			City									Zip	p Code	
		Mesa								85	215			
Operator Does Business As:			0	perator Desig	nator Co	de:								
- Type of U.S. Certificate(s) Held: N														
Air Carrier Operating Certificate(s):														
Operating Certificate: Operator Certificate:														
Regulation Flight Conducted Under: Part 91: General Aviation														
Type of Flight Operation Conducted	: Instructional													
		FACTI	UAL RE	EPOF	RT - AVIATI	ON							Page 2	

National Transportation Safety Board

FACTUAL REPORT

AVIATION

NTSB ID: DEN02LA019

Occurrence Date: 01/11/2002

AVIATION TYBON	Occurrence Type: Accident													
First Pilot Information														
Name					City					State	Dat	te of Birth	Age	
On File					On File	ile				On File	Oı	n File	41	
Sex: M Seat Occupied:	Left	Prir	ncipal Profes	sion: Civilia	n Pilot	t Certificate Number: On File								
Certificate(s): Flight														
Airplane Rating(s): Singl														
Rotorcraft/Glider/LTA: Helicopter														
Instrument Rating(s): Helicopter														
Instructor Rating(s): Helicopter														
Type Rating/Endorsement for Accident/Incident Aircraft? No Current Biennial Flight Review? 02/20											2/200	0		
Medical Cert.: Class 2	aivers/lii	m.		D	ate of Las	t Medic	al Exan	n: 08/2001						
· ·														
		This Make and Model	Airplane Single Engine	Airplane Mult-Engine	Night	t	Actual	nstrumen	t Simulated	Rotorcraft		Glider	Lighter Than Air	
Total Time	9436	229			2	624		5 2			9419			
Pilot In Command(PIC)	9200	220						_		_	9200			
Instructor	6307	105			-			_		_	6307			
Last 90 Days	146	86						-			146			
Last 30 Days Last 24 Hours	37	49			+	-		\dashv		+	36			
Seatbelt Used? Yes		lder Harness	Used? Yes		<u> </u>	Гохісо	ology Per	forme	d? No			nd Pilot? Ye	S	
	<u> </u>													
Flight Plan/Itinerary														
Type of Flight Plan Filed: No	ne													
Departure Point						State	P	Airport Identif		ier Departur		e Time	Time Zone	
Englewood					1	СО	A	APA		0750			MST	
Destination						State Airpo		Airport Identifier						
Local Flight						APA								
Type of Clearance: None														
Type of Airspace: Class E	≣													
Weather Information														
Source of Briefing:	ercial Weat	her Service												
Method of Briefing: Unknow	wn													
											Page 3			

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: DEN02LA019

Occurrence Date: 01/11/2002

Occurrence Type: Accident

	FIYBOR		Occurrent	Occurrence Type: Accident											
Weather	Weather Information														
WOF ID	Observation Time	Time Zone	WOF Elevati	on	WOF Distance From Accident Site					Direction From Accident Site					
APA	0853	MST	5883 Ft.	5883 Ft. MSL							80 Deg.	Mag.			
Sky/Lowes	t Cloud Condition: Scatt				150 Ft. A	(GL	Condition of Light: Day								
Lowest Ce	iling: Broken		250 Ft.	AGL	Visibi	lity:	10	SM	Altiı	meter:	30.24	"Hg			
Temperatu	ıre: 3 °C [-12 °C	-12 °C Wind Direction: 220 Density Altitude: 58								Ft.				
Wind Spee	ed: 8		Weather Condtions at Accident Site: Visual Conditions												
Visibility (R	RVR): Ft.	Visibility (R)	√V)	SM	Intensity	of Precip	itation:								
Restriction	Restrictions to Visibility: None														
Type of Precipitation: None															
Accident Information															
Aircraft Dar	mage: Substantial		Aircraft Fire	Aircraft Fire: None					Aircraft Explosion None						
Classificati	on: U.S. Registered/U.	.S. Soil													
- Injury Su	mmary Matrix	Fatal Se	rious Mino	or	None	TOTAL									
First Pi	lot														
Second	d Pilot				1		1								
Studen	t Pilot						7								
Flight In	nstructor				1		1								
Check	Pilot														
Flight E	ngineer														
Cabin A	Attendants														
Other C	Crew														
Passen	gers			1		1									
- TOTAL A			3		3										
Other G	Ground														
- GRAND	TOTAL -				3		3								

National Transportation Safety Board

FACTUAL REPORT AVIATION

NTSB ID: DEN02LA019

Occurrence Date: 01/11/2002

Occurrence Type: Accident

Α	S	lm	in	ist	rat	ίv	e l	Ini	fο	rn	n۶	ati	O	n
,	10			ıυι	ıuı		U		\cdot		110	461	v	

Investigator-In-Charge (IIC)

James F. Struhsaker

Additional Persons Participating in This Accident/Incident Investigation:

Bruce Hanson FAA FSDO 26805 E. 68th Ave, #200 Denver, CO 80249